

# PENTAX



## TRAPS TR POWER PACK

の使い方

ペンタックスTRパワーパックはAF400TやAF080Cリングライト用の外部電源で、単2型電池6本を使用し、発光回数の増加、発光間隔の短縮ができます。付属のストラップで肩から下げると、ケース裏側のホックをはずして腰のベルトに下げて使えます。


The TR Power Pack is a transistorized power unit for the Pentax AF 400T or AF080C electronic flash unit. The power pack utilizes six "C" cell batteries for power which is stored in a reservoir by the unit's transistor circuitry as a ready supply for fast recycle and successive shooting operations.

Accessories supplied with the power pack include the carrying case and an accessory shoulder strap, which is detachable for carrying the pack belt-style.



作動表示ランプ  
Power lamp

スイッチ  
Power switch



ストラップ


プラグ  
Plug

ケース  
Case

電池室  
Battery chamber



Shoulder strap



### Operating the Power Pack

1. Take the power pack out of the case. Insert six "C" cell batteries in the battery chamber in accordance with the plus/minus (+) (-) markings in the chamber. Replace the power pack in its case.
2. Plug the TR Pack into the external power socket of the flash unit. Set the flash unit power switch to the external power setting (EXT.)
3. Turn the power switch for the power pack to ON. When the circuitry has stored its power supply the power lamp will light.
4. Switch the flash unit ON. Photos may be taken anytime after the flash unit's ready lamp lights.

- When not using the TR Power Pack for long intervals, slide the power switch for the power pack to OFF; Battery energy will deplete if the switch is left on, even with the flash unit switched off.
- When the flash unit's ready lamp no longer lights within 30 seconds, replace all six batteries together.
- When the power pack has been out of use for sometime, longer intervals are required for the transistor's to store energy, hence the power lamp will not light for several seconds after switching on the power.

**IMPORTANT: The TR Power Pack utilizes high voltage circuitry. When operating the unit, do not touch metal parts of the plug or insert metal objects of any type into electrical contact terminals. If the unit malfunctions, DO NOT DISMANTLE IT. Bring the unit to an authorized service center for repair.**

Before operating this TR Power Pack, also refer to the "BATTERIES" page of the AF400T or AF080C operating manual.

## 仕様

電池——単2型電池6本

アルカリリマンガン電池

LR-14など

Ni-Cd蓄電池

NR-Cなど

〔Ni-Cd蓄電池の充電は電池指定の充電器を使用してください。〕

発光回数・間隔——

ストロボ AF400T リフレ AF080C ライト	発光回数	発光間隔
	約210回	約7秒
	約600回	約3秒

〔光量FULL〕

大きさ——104〔幅〕×168〔高〕×48〔厚〕mm

重さ——490g〔電池別〕

## SPECIFICATIONS

**Power source:** Six alkaline "C" cell batteries (rechargeable Ni-Cad batteries also usable in conjunction with a commercially available recharger unit).

**Number of flashes/recycling times:**

Flashes	Number of flashes	Recycling time
AF400T	Approx. 210	Approx. 7 sec.
AF080C	Approx. 600	Approx. 3 sec.

**Size:** 104mm x 168mm x 48mm

**Weight:** 490 grams (without batteries)

**Accessories:** Case w/shoulder strap



旭光学工業株式会社

●114 東京都港区新町2丁目28番9号 (3073)1(F)

旭光学商事株式会社

●100 東京都千代田区水田町1丁目11番1号 (340)2051(F)

### ●引継ぎは次の名所へ

ペンタックスストア——平160 東京都新宿区西新町2丁目1番1号 東電三井ビル(5階)  
 東京——平104 東京都中央区銀座5丁目10番地  
 札幌——平600 札幌市中央区南一条西1丁目1番27号  
 仙台——平900 仙台市青葉区大崎十番10号 山崎ビル  
 山形——平721 山形市西町2丁目2番10号 山崎ビル  
 新潟——平721 新潟市中央区西1丁目1番9号 山崎ビル  
 名古屋——平520 名古屋市中区栄1丁目1番5号  
 京都——平600 京都市中京区中京1丁目1番5号  
 広島——平730 広島市中区中區12番12号 広島グリーンビル  
 福岡——平810 福岡市博多区中洲4丁目3番5号  
 新幹線——平601 東京都港区新橋1丁目53番地 日本橋駅前ビル  
 東京——平400 東京都千代田区千代田2番1号 任交駅前ビル  
 仙台——平900 仙台市青葉区新町2丁目2番27号 大通五番ビル  
 京都——平700 京都市中京区東区東1丁目10番地  
 ●減価償却期間——平104 東京都中央区銀座5丁目10番地

※記載内容の仕様などの一部が変更される場合があります。

02-8406